As per in Creo Drawing

## Blank Dimensions

After bending dimensions

In Real time Manufacturing

Blank Dimensions

After Bending Dimensions