

PTC® Live Global

CUST 237 - The One Size Fits All Change Process

Stephen Drzewiczewski – iRobot Corporation
Sr. Manager of Collaborative Applications

Tuesday June 9th, 5:00 – 5:45 PM



PTC® Live
Global

What happens when a “*simple,*” **urgent** change takes more time than Senior Management is willing to wait?




The One Size Fits All Change Process

Agenda

- Introduction
- Process Redesign Approach
- Usability Improvements
- The Checklist Utility
- Factory Implementation Tasks
- Process Reporting




Project Timeline



Characteristics of the Change Process:

- All Tasks were blocking (Gated) tasks
- CRB and CIB had an average of 5 approvers each
- Tasks always happened, even when not needed (*Validate Change, Cost Analysis & Impact Analysis*)
- Each Work Task had multiple gated approval steps
- Factory Implementation tasks not well understood
- No Escalation of approval tasks
- No well defined metric points



5

Executive Requirements

Guiding Principals

- Trust employees to do the right thing and hold them accountable for their decisions
- Eliminate wasted time and effort
 - Reduce the number of gates
 - Reduce the number of approvers
 - Take non-blocking work off the critical path
 - Replace serial steps with parallel ones whenever possible
- Flexible process to accommodate all types of changes, regardless of the BU
- Automate escalation to ensure timely movement through the gates
- Conform our tools to our desired process, not the other way around
- Maintain process performance metrics and review quarterly



6

Roles and Responsibilities


- **Program Manager (PM) & Operations Program Manager (OPM)**
- **Approval of the Change Request**
 - Responsible for working with the program team and business unit to understand the requested change
 - Empowered to approve the time, money and resources required to carry out the change
- **Define checklist of additional tasks for the proposed change**
- **Approval of the Change Notice**
 - Responsible for making sure all of the necessary work has been completed for the change
 - Understand the impact of the change to manufacturing and inventory
 - Empowered to approve the implementation of the change into the factory




Approach

- **Production Beta**
 - Select Products from each Business Unit
 - Trained the Beta users and management team
 - Identified bugs and remediated
- **Feedback Sessions**
 - After one month of the Production Beta, two facilitated feedback sessions were held
 - Identified everything that worked (acknowledge/verify that the process is better than when we started)
 - Identified areas for additional improvement
 - Organized issues into themes
 - Prioritized
 - After the sessions there was agreement from management on what would be worked on for the next version
- **Iterative Design**
 - ECR form evolved to better define the Change
 - Checklist evolved from an Excel file to a custom utility

Before



After



Process Improvements:

- Fewer blocking (gated) tasks [shown in white]
- PM & OPM are only mandatory approvers
- "Work" tasks (checklist tasks) created but non-blocking
- Checklist tasks are phased to occur when they are required and make sense
- Work task has one mandatory task and one optional review task
- Escalation of approval tasks
- Defined metric points

Usability Improvements

Before

- No iRobot specific instructions / help
- Single Description field, what should go here?
- No field for Priority
- Confusing field “Classification” only used on D&S
- Field for Problem Report Number (Legacy), but no tie-in to Bugzilla

The screenshot shows a 'New Change Request' form with the following fields:

- Product: Change Product
- Type: Change Request
- Attributes:
 - Number: (Generated)
 - Name: Roomba 500 and 600 - Insert failing due to insufficient clearance
 - Category: Design Issue
 - Description: There isn't enough clearance for the 4453438 insert to fit smoothly into the 4453437 plate, and that is causing the insert to fail faster. In addition, the rim of the insert sticks up above the plate, and causes...
 - Classification: Class 2 Change
 - Problem Report Number: (Empty)
 - Special Instructions: Depending on how much inventory there is left, we may need to scrap or use up existing. Cancel any new orders.

11

After

- Link to a “Gold Standard” for filling out the form at the top
- Logical attribute groups
- Three fields to direct user how to describe a Change Request
- Ability to link to Bugzilla bug(s)
- Made Category a required field
- Request Priority field drives approval deadlines
- Allow ECR Author to provide input on disposition
- More intuitive questions to drive classification of change



The screenshot shows the updated 'New Change Request' form with the following fields and annotations:

- Special Instructions: Click here for "Gold Standard" examples on filling out a Change Request!
- Product: Change Product
- Type: Change Request V2
- ECR Summary Information:
 - Title: Roomba 500 and 600 - Insert failing due to insufficient clearance
 - Category: Design Issue
 - Request Priority: Medium
 - Requested By: John Doe
 - Target State: Production
- ECR Description:
 - Current Condition: into the 4453437 plate, and that is causing the insert to fail faster. In addition, the rim of the insert sticks up above the plate, and causes an interference with other objects.
 - Proposed Solution: Need to add more clearance to the hole and add a counterbore to accommodate the rim of the insert so it can lay flush.
 - Reason for Change: When the insert fails, the plate becomes disconnected and may fall off, which then causes the robot to stop working.
- ECR Additional Information:
 - Bugzilla Defect Number: 433693
 - Recommended Disposition of WIP: Exhaust Existing Inventory
 - Additional Notes: Depending on how much inventory there is left, we may need to scrap or use up existing. Cancel any new orders.
- Class of Change:
 - Government or medical contract requirements: None
 - Is the change backwards compatible?: Yes

Configuration Steps

- Modified the OOTB JSP page
 - codebase\netmarkets\jsp\changeRequest\create.jsp
 - Added a link to detailed work instructions
- “Create New Layout” organized using Attribute Groups
- Bugzilla Defect Number Input Field
 - Regular Expression Constraint to only allow numbers and commas

```
<ov:initializeChangeWizard changeMode="CREATE" varianceEffectivity="false" annotationUIContext="change"
changeItemClass="wt.change2.ChangeRequestIfc" />
<div class="x-panel-header attributePanel-label" style="text-align:center">Special Instructions: <a href=
"http://<server-name>.irobot.com/workflows/instructions/03_Change_Request_2/For_Gold_Std.html" target="_blank"
> Click here for "Gold Standard" examples on filling out a
Change Request</a></div>
</ov:wizard helpSelectorKey="change_createChangeRequest" buttonList="DefaultWizardButtonsWithSubmitPrompt">
```




- Bugzilla Link Field
 - Added a Calculated Attribute to display the Bugzilla URL
 - Used the formula to concatenate the server URL plus the bugzillaDefectNumber
 - "http://<server name>.irobot.com/buglist.cgi?quicksearch="+bugzillaDefectNumber

13

Email Task Subjects


Before

- Generic task name in e-mail subject



After

- Subject of e-mail contains more information to understand the task and urgency without opening it




14

Email Task Message Content

Before

- Must navigate into the assigned task to know what the ECR/ECN is about



After

- In the task email
 - ECR summary
 - Links to checklists and Bugzilla bugs

You have been assigned a **MEDIUM Approve Change Request and Define Checklist (PM) ECR37836**. Roomba 500 and 600 - Insert failing due to insufficient clearance.


Instructions: For detailed instructions, as well as a link to additional reference material, click on the image below:

PM Checklist	PM Checklist
Category:	DESIGN_ISSUE
Bugzilla link:	http://robot.com/buglist.cgi?quicksearch=433593
Current Condition:	There isn't enough clearance for the 4433438 insert to fit assembly into the 4433437 plate, and that is causing the insert to fail faster. In addition, the rim of the insert sticks up above the plate, and causes an interference with other objects.
Proposed Solution:	Need to add more clearance to the hole and add a counterbore to accommodate the rim of the insert so it can lay flat.
Reason For Change:	When the insert fails, the plate becomes disconnected and may fall off, which then causes the robot to stop working.


Email Task Message Content

Checklist Links and Task Instructions

- Checklist Links
 - String Process Variables for PM and OPM Checklist Links.
 - String value is the URL generated with an external Java method



- Task Instructions
 - Formatted with HTML
 - Process Variables displayed using the {variable name} notation
 - Inline CSS statements and existing CSS Classes used to enhance readability




Before



After

- Added a custom tab to display a table of “Checklist Tasks”



17

Adding a Custom Tab

- Created custom Configurable Table Builder
 - Followed the 10.1 Customizer's guide
 - Configurable Table adds Table View functionality
- Modified codebase\config\mvc\custom.xml
 - Register new builder

```
<beans xmlns="xmlns:mvc="http://www.ptc.com/schema/mvc"
xsi:schemaLocation="http://www.ptc.com/schema/mvc
http://www.ptc.com/schema/mvc/mvc-10.0.xsd">
<mvc:builder-scan base-package="ext.iRobot.mvc.builders.table"/>
</beans>
```

```
@ComponentBuilder("ext.iRobot.mvc.builders.table.iRobotECNChecklistTableBuilder")
iRobotECNChecklistTableBuilder extends AbstractConfigurableTableBuilder {

//Method to return a Persistable, in this use case a WTChangeOrder2
@Override
public QueryResult buildComponentData(ComponentConfig arg0, ComponentParams arg1){...}

//Method to return a configured table to include Label, ID, properties and columns to be displayed
@Override
public ComponentConfig buildComponentConfig(ComponentParams arg0){...}

@Override
public ConfigurableTable buildConfigurableTable(String tableId) throws WTEException {...}

//Class to get the OOTB TableViews and Define new Views
private static class MyConfigurableTable extends JCAConfigurableTable {...}
}
```

- Created Resource Bundle to store Label and Tooltip
- Modified codebase\config\actions\custom-actions.xml

```
navigation.caTable.tooltip.value=Checklist Status
navigation.caTable.tooltip.comment=Checklist Status
navigation.caTable.description.value=Checklist Status
navigation.caTable.description.comment=Checklist Status
```

```
<objecttype name="navigation" resourceBundle="ext.iRobot.iRobotActions" class="">
<action name="caTable" renderType="Default">
<component name="ext.iRobot.mvc.builders.table.iRobotECNChecklistTableBuilder"
windowType="page" urlParams="asynct=true" />
</action>
...
</objecttype>
```



- Modified codebase\config\actions\custom-action-Models.xml

```
<!-- Tabs for Change Notice Info Page -->
<model name="changeNoticeInfoPageTabSet" >
<submodel name="changeNoticeDetailsTab"/>
<submodel name="implementationPlanTab"/>
<submodel name="simplifiedImplementationPlanTab"/>
<submodel name="changeNoticeProcessTab"/>
<submodel name="changeObjectsHistoryTab"/>
<!-- <action name="sysnavTab" type="sysnav"/> -->
<action name="caTable" type="navigation" resourceBundle="ext.iRobot.iRobotActions" />
</model>
```

18

Training Improvements

- Job specific training
 - PM/OPM
 - General task assignees
- Quick Reference Cards
- Updated instructions and workflow process images on ECR/ECN tasks
- Web-based training site on new process



Checklist Tool

Leveraging an Iterative Process to Release Functionality Quicker





Enabling a Flexible Process

- Ability to select work from pre-defined list of tasks
- Ability to add “one-off” tasks not on pre-defined list
- Specify task assignee and optional reviewer
- Specify timing of task
- Easy to use



Brainstorming

- Predefined tasks that could be selected from
- Ad-Hoc workflow task to define all tasks
- Manually create Implementation Tasks
- Excel spreadsheet
- Custom solution



Excel

- Avoid “Analysis Paralysis” - Validate the process and gather feedback
 - Determine if pre-defined list of tasks was complete
 - Identify correct task type and start times
 - Measure the reliability and ease of use of process
- Not an optimized process – too many “clicks”. Required Configuration Manager to create Implementation Tasks

Task Needed	Task Name	Assignee	Reviewer (if applicable)	Task Description	Start Time	Additional Comments	Task Type
	Complete Electrical Design Changes	Cliff C		Electrical design database is updated All electrical design documentation reflects the design change involved in the ECR. Updated schematics, layout, Gerber files, etc. reviewed and checked in.	Immediately		Design
X	Complete Mechanical Design Changes	Cliff C	Jason S	Mechanical design database is updated All mechanical design drawings reflect the design change involved in the ECR. Models and Drawings updated, reviewed and checked in.	Immediately	Add 125° to clearance hole diameter to avoid interference, and drill a counterbore to accommodate the head of the screw. Add a cross-section to the front view on the drawing.	Design
	Complete Software Changes			Software changes are complete. Software updates are complete, reviewed and checked into S&B and SPC/Shop.	Immediately		Design
	Compliance and Safety			Software changes required for this ECR are complete. Software updates are complete, reviewed and checked into S&B and SPC/Shop. Certification testing is complete and required product certifications have been received. <small>For more information on our contributions to resolution as a result of...</small>	Immediately		Design Analysis

Custom Utility – Form – Incorporate User Feedback

- Built using ExtJS 3.4 – used by PTC for their development
- Similar look and feel of Windchill
- Included ECR Attributes on page
 - Minimized the need to go back and forth between ECR details page and Checklist form.
- Allows for Drag and Drop user interaction
- Lists of tasks maintained in an XML file
 - Allows for real time additions and deletions




Task Name	Task Type	Assignee	Reviewer	Start Time	Comments
Complete Electrical Design Changes	Design	Cliff and C	Jason S	Immediately	
Complete Mechanical Design Changes	Design	Cliff and C	Jason S	Immediately	Add 125° to clearance hole diameter...
Complete Software Changes	Design	Cliff and C	Jason S	Immediately	
Compliance and Safety	Design Analysis	Amy D		Immediately	
ECR Requestor Review	Design Analysis	Brian J		Immediately	

```

<?xml:namespace>
<checkboxlistTask>
  <taskName>Complete Electrical Design Changes</taskName>
  <taskDescription>Electrical design database is updated
  </taskDescription>
  All electrical design documentation reflects the design change involved
  in the ECR. Updated schematics, layout, Gerber files, etc. reviewed
  and checked in.
</checkboxlistTask>
<checkboxlistTask>
  <taskName>Complete Mechanical Design Changes</taskName>
  <taskDescription>Mechanical design database is updated
  </taskDescription>
  All mechanical design drawings reflect the design change involved in the
  ECR. Models and Drawings updated, reviewed and checked in.
</checkboxlistTask>
    
```


Custom Utility – Data Storage

- ExtJS supports encoding output to JSON
- Save to Windchill button executes the addAttachment function, which executes an AJAX request



```

var addAttachment = function() {
    //Initialize array to hold the selected items
    var selectedItems = [];
    //Get the data store in the selectedItems grid
    var selectedItemsStore = selectedTasksGrid.getStore();

    //Iterate through each item in the data store.
    selectedItemsStore.each(function(item) {
        //Add each item in the SelectedItemsStore to the array.
        selectedItems.push(item.data);
    });
    //Send data to server via AJAX request
    Ext.Ajax.request({
        url: 'netmarket/jsp/ext/iRobot/ecrChecklistConfigToolFormProcessor.jsp',
        method: 'POST',
        success: function(c,o) {
            if (c.responseText === 'true') {
                Ext.MessageBox.show({
                    title: 'Checklist Saved',
                    msg: 'The "' + taskOwner + '" Checklist has been saved!',
                    icon: Ext.MessageBox.INFO,
                    minWidth: 300,
                    buttons: Ext.MessageBox.OK
                });
            }
        },
        //Set parameters to be sent to AJAX request
        params: {selectedTasks: Ext.util.JSON.encode(selectedItems), number:number, taskOwner:taskOwner}
    });
}
    
```

- The AJAX request calls a Java Servlet
 - Sets three variables
 - Executes a server side Java method addAttachmentToECR

```

<%@ page import="java.io.*; java.util.*; ext.iRobot.*" %><%
String ecrNumber = request.getParameterValues("number")[0];
String fileName = request.getParameterValues("number")[0] + "." + request.getParameterValues("taskOwner")[0] + "_selected_tasks.json";
String fileContent = request.getParameterValues("selectedTasks")[0];
%><%= EcrChecklistHelper.addAttachmentToECR(ecrNumber, fileName, fileContent) %>
    
```

Checklist 2.0 - Steps to Complete Checklist

1. Navigate to checklist from approval task or e-mail notification
2. Edit the checklist
 - Select tasks needed
 - Select Assignee
 - Select Optional Reviewer
 - Enter Comments
3. Save checklist

PM Checklist link:	PM Checklist
Category:	DESIGN_ISSUE
Bugzilla link:	http://[redacted].irobot.com/buglist.cgi?quicksearch=4336
Current Condition:	There isn't enough clearance for the 445348 insert to fit smoothly into
Proposed Solution:	Need to add more clearance to the hole and add a counterbore to acco
Reason For Change:	When the insert fails, the plate becomes disconnected and may fall off

Inputs

Comments:

PM Checklist Configuration Tool: PM Checklist

Routing Options:

Approve

Cancel

Rework

Assignee

Clifford C

Amy D

Brian J

Chris L

Clifford C

Deborah K

Garrett B

Jason S


ECR Attributes (Click = to expand)

Task Name	Task Name	Task Type	Assignee	Reviewer	Start Time	Comments
<input type="checkbox"/> Add New Task						
<input type="checkbox"/> Complete Electrical Design Changes		Design	Clifford C	Jason S	Immediately	Add .125" to clearance hole diameter...
<input type="checkbox"/> Complete Mechanical Design Changes		Design Analysis	Amy D		Immediately	
<input type="checkbox"/> Complete Software Changes		Design Analysis	Brian J		Immediately	
<input type="checkbox"/> Compliance and Safety						
<input type="checkbox"/> Customer Service Impact Analysis						
<input type="checkbox"/> ECR Requestor Review						
<input type="checkbox"/> End of Life Analysis						
<input type="checkbox"/> Prepare Service Communication						
<input type="checkbox"/> SEIT - Update and Verify System Requirements						
<input type="checkbox"/> Update Product Packaging and Documentation						
<input type="checkbox"/> Update SKU BOMs						

Save to Windchill

Checklist 2.0 – Workflow Modification

- Configuration Manager still creates ECN
- The ECR workflow was modified to automatically create Implementation Tasks
- Configuration Manager still needs to add Affected and Resulting Data to the newly created tasks



Factory Implementation Tasks

Continuing Iterations to Add New Functionality Not Originally In Scope

Factory Implementation Requirements

- Record Implementation Dates by Contract Manufacturer
 - Must support multiple Contract Manufacturers
- Record Planned & Actual Implementation Dates
- Post Implementation go back to ECN and see dates
- Easy to read report for Resolved ECNs to include Planned and Actual Implementation dates.
- Desired to only track Implementation Date at the ECN level, not at the individual part level



Factory Implementation

- Created New Soft Type of Change Activity for Factory Implementation Task
 - Added Three Attributes
 - Contract Manufacturer
 - Planned Implementation Date
 - Actual Implementation Date


Contract Manufacturer:	Planned Implementation Date:	Actual Implementation Date:
<input type="text"/>	2014-11-27 <small>yyyy-mm-dd</small>	2014-11-30 <small>yyyy-mm-dd</small>

- OPMs Enter Planned Implementation Date

* Planned Implementation Date (MM/DD/YYYY):

- Assignee enters the Actual Implementation Date

* Actual Implementation Date (MM/DD/YYYY):



- Each Factory is represented by a WTPart to be used as an Effectivity Context
- A Java method sets Effectivity to the Actual Implementation Date to the Resulting Data of each Factory Implementation Task (Change Activity)

```
//takes the actual implementation date and puts it into the effectivity value that will be applied to the WTParts.
ext.iRobot.workflow.ChangeWorkflowHelper.setEffectivity((wt.change2.WTChangeActivity2)primaryBusinessObject);
```




Factory Implementation

- The Checklist Utility was extended to Include Factory Implementation Tasks for each Factory
 - Included XML element for Contract Manufacturer and Change Task Type

```

<checkboxlistTask>
  <taskName>Factory Implementation at Factory 1</taskName>
  <taskDescription>Enter the planned and final implementation data for the selected factory.</taskDescription>
  <taskType>Implementation</taskType>
  <startTime>Post_Design</startTime>
  <taskOwner>QM</taskOwner>
  <taskIconURLType>MCTFE[wi_change2_MPCChangeActivity]com.1robot.www.1RobotFactoryImplementationTask</taskIconURLType>
  <taskContractManufacturer>Factory 1</taskContractManufacturer>
</checkboxlistTask>
<checkboxlistTask>
  <taskName>Factory Implementation at Factory 2</taskName>
  <taskDescription>Enter the planned and final implementation data for the selected factory.</taskDescription>
  <taskType>Implementation</taskType>
  <startTime>Post_Design</startTime>
  <taskOwner>QM</taskOwner>
  <taskIconURLType>MCTFE[wi_change2_MPCChangeActivity]com.1robot.www.1RobotFactoryImplementationTask</taskIconURLType>
  <taskContractManufacturer>Factory 2</taskContractManufacturer>
</checkboxlistTask>

```



- Java Method to create Implementation Tasks was modified to take Task Type as an input
- Status Tracking Tab required no code change
 - Edited existing Table Views to add three columns for Contract Manufacturer, Planned and Actual Implementation Date
 - Added new Table View displaying only Factory Implementation Tasks

Number	Name	Assignee	Resource	Job Status	Synchase	Contract Manufacturer	Planned Implementation Date	Actual Implementation Date
62755	Complete Mechanical Design Changes	Michael D	Not Required	Completed	Design			
62756	End of UR Analysis	Deborah K	Not Required	Waiting	Supplemental_Post_Release			
62757	Update SLD BOMs	Steve Driscollowski	Not Required	Completed	Design			
62758	Factory Implementation at Factory 1	Steve Driscollowski	Steve Driscollowski	Active	Supplemental_Post_Release	Factory 1	2015-08-18	
62759	Factory Implementation at Factory 2	Michael D	Steve Driscollowski	Active	Supplemental_Post_Release	Factory 2	2015-08-21	

33

Reporting

Monitoring the Process

Manager Report – Overdue Approval




- Identify ECR/ECN Approval tasks that were approaching their deadlines or overdue.
- Data Monitors used to deliver report to Managers daily if threshold of 1 was met

ECN Number	Activity Name	User Name	Contact Name (name)	Due Date	Days Over Due
ECN58419	Approve Change Notice (OPM) ECN58419	Joseph H	R	2014-07-29 10:03:34 EDT	1
ECN58419	Approve Change Notice (OPM) ECN58419	Robert P	R	2014-07-29 10:03:34 EDT	1




ECN Implementation Report

- List ECNs and their Factory Implementation Tasks
 - Saved Reports allow a multiple use cases for a single report definition
 - Charts Allow quick visualization of data and filtering



Context	ECN Number	ECN Name	ECN State	Contract Manufacturer	Planned Implementation Date	Actual Implementation Date	Task State	Task Status
			Released		2015-05-15		Implementation	Active
			Released				Implementation	Active
			Released				Planning	Active
			Released				Planning	Active
			Released		2015-05-11		Implementation	Active
			Released		2015-06-08		Implementation	Active
			Released		2015-05-01		Implementation	Active
			Released		2015-06-15		Implementation	Active
			Released		2015-06-15		Implementation	Active



Factory Implementation Tracking Status Report

- Lists ECN details, Factory Implementation details and the resulting data
- Replaced Excel spreadsheets used by Far East team to track ECN Implementation

Factory #	ECN #	ECN Description	ECN rev'd Date	ECN Status	Task #	Project	Category	PIC(Robot)	Window P/N	Part Description	Revision	Change Type	Planned Implementation Date	Actual Implementation Date	Picture of the picture can be ...	Related Tool #
			2015-05-13	Released	65075			Ivan Zh			G	Running change	2015-05-15			
			2015-05-26	Released	65111			Jody G			M	Running change				
			2015-05-26	Released	65111			Jody G			N	Running change				
			2015-06-01	Released	65355			Jody G			B	Running change	2015-06-15			
			2015-05-26	Released	64578			Ray Zh			F	Running change				
		Removed Data	2015-05-26	Released	65110			Jody G		Removed Data	M	Running change				
			2015-05-26	Released	65110			Jody G			N	Running change				
			2015-05-01	Released	65153			Ray Zh			B	Running change	2015-05-01			
			2015-05-01	Released	65153			Ray Zh			C	Running change	2015-05-01			
			2015-05-01	Released	65153			Ray Zh			F	Running change	2015-05-01			
			2015-05-08	Released	65160			Ray Zh			C	Running change	2015-05-11			
			2015-06-01	Released	65316			Jody G			B	Running change	2015-06-15			
			2015-06-01	Released	65392			Ritche C			G	Running change	2015-06-08			

- Started with executive buy-in and commitment of required resources
- Established clear roles and responsibilities
- Increased Overall Process Efficiency
 - Decreased required Approvers from 5 to 2
 - Limited blocking tasks
- Streamlined the User Interface to help users create ECRs with the right information
- Fully capture the work required to complete an ECN
- Leveraged an Iterative Process to introduce changes to the process faster
- Far East Operations embraced new process, allowed them to focus on implementing ECNs



- Your feedback is valuable
- Don't miss out on the chance to provide your feedback
- Gain a chance to win an instant prize!
- Complete your session evaluation now

PTC® Live Global

PTC® PRODUCT & SERVICE
ADVANTAGE™